

# MODULARline & SOLIDline SoftPerfection/-Zero



## Löschen der Endlagen

---

① ▽ ▲ 1 Sek.

➡ 5 Sek. (Pause)

---

② ▼ △ 1 Sek.

➡ 5 Sek. (Pause)

---

③ ▽ ▲ 1 Sek.

➡ 5 Sek. (Pause)

---

④ ▽ ▲ 1 Sek.

➡ 5 Sek. (Pause)

---

**FERTIG!** 