MODULARline & SOLIDline
SoftPerfection/-Zero

Delete the end stops

G

❶ ▽▲ 1 sec

➡ 5 sec (break)

❷ ▼△ 1 sec

➡ 5 sec (break)

❸ ▽▲ 1 sec

➡ 5 sec (break)

❹ ▽▲ 1 sec

➡ 5 sec (break)

READY! 👍