


MODULARline & SOLIDline SoftPerfection/-Zero




Supprimer les fins de course

①   1 sec

 5 sec (pause)

②   1 sec

 5 sec (pause)

③   1 sec

 5 sec (pause)

④   1 sec

 5 sec (pause)

FINI!

